

# McKenzie County Solid Waste Management Department

\*\*\*\*\*

## List of prohibited wastes

1. Liquids of any kind. (Except household quantities)
2. Un-rinsed pesticide containers.
3. Used oil / waste oil.
4. PCB waste / oil.
5. Paints can be taken if they are dry. (No liquids)
6. Mercury containing devices. (Fluorescent lights, thermostats, thermometers, etc.)
7. Ballasts, capacitors, etc.
8. Copier toners.
9. Sludge's of any kind.
10. Manure in large quantities.
11. Septic tank sludge or tailings.
12. Fertilizers.
13. Flammables, corrosives, bio-hazards, reactives (Part A/B), poisons, hazardous wastes, radioactive wastes, blood borne pathogen wastes, toxic wastes or unknown wastes. These regulations can be found in the Code of Federal Regulations. (40 CFR 258) and (40 CFR 261.10).

**If you have a question about what you have, please call. We can figure it out, take it or find a solution for you if it's something we can't receive.**

### Pit liners

Pit liners will not be accepted at the McKenzie County landfill. It does not matter what color they are, how big they are or where they came from. If they are dirty, soiled or covered in crude they will not be accepted. If it hits the floor of the landfill you will be fined \$1000. You will also be charged a \$100 loader fee to reload the liner back into your truck. All rejected loads are reported to the State of North Dakota even if the liner was tested and deemed non-radioactive.

### Filter socks

Filter socks will not be accepted at the McKenzie County landfill. If you drop filter socks on the landfill you will be fined \$1000 for the first sock and \$1000 for each additional sock that hits the ground. The driver will count all of the socks and place them back in the truck or container with a County employee present. All rejected loads are reported to the State of North Dakota even if the socks are tested and deemed non-radioactive.

All metals must be separated under North Dakota State Law. We retain the right to reject your load if it is mixed and full of metals. If you drop the load on the landfill you will receive a \$240 fee. You will also receive a \$100 loader fee for us to move your metal to its proper location.

## **List of metals that must be separated**

1. Pipe
2. Wire
3. Cable
4. Iron
5. Bikes
6. Appliances
7. Metal shaker screens
8. Derek floors
9. Expanded metal
9. Etc, etc, etc.

**McKenzie County reserves the right to refuse service to anyone.**

\*\*\*\*\*

**McKenzie County also reserves the right to refuse any load or part of a load if it does not meet our requirements. Remember, we operate under Federal and State of North Dakota guidelines.**

\*\*\*\*\*

**The McKenzie County landfill is absolutely not responsible for flat tires or damage to tires. This is a landfill and you take full responsibility for flats or damage. We do our very best to pull metal out but again, this is a landfill.**

**Should you have any questions, comments or concerns please contact the following;**

**Rick Schreiber**

**Director**

**McKenzie County Solid Waste Department**

**1.701.586.3445 or [rschreiber@co.mckenzie.nd.us](mailto:rschreiber@co.mckenzie.nd.us)**